



UNITY POINT HEALTH - MERITER LABORATORIES

Pathology Review Updates

2/20/26

Effective immediately, manual differentials have been removed from the RPATH2 battery. Manual differentials will continue to be completed on CBCs that reflex according to established internal criteria. This change aligns our process with UW Health testing requirements, which specify that either an automated *or* a manual differential is required.

Pathology Review		
	CURRENT	NEW
EPIC EAP	LAB5204	LAB5204
SQ Code	RPATH2	RPATH2
Components of the Battery	PATRV (pathology review) and QDIFFM (manual differential)	PATRV (pathology review)

Additional information can be found in the Meriter Laboratories online Test Directory (link below).

[Meriter Laboratories Test Directory | Home](#)

If you have any questions, please call the UnityPoint Health - Meriter Laboratories Client Services Department at 608-417-6529 or 1-800-236-0465.