

UNITYPOINT HEALTH - MERITER LABORATORIES
TEST ANNOUNCEMENT

Changes to ANCA testing at ARUP

08/27/2021

Effective, **Immediately**, ARUP made changes to their ANCA orders, so we have updated our system to reflex the changes below.

Previous testing:	New Testing:
ANCA PANEL (VASCULITIS) W/ RFLX TITER EAP: LAB6431 SQ Code: ANCRFA CPT: 86255 Performing Lab: ARUP Reported: ANCA pattern With potential reflex to titer Reflex MPO/PR-3 (ANCA) Antibodies EAP: LAB3503 SQ Code: ANCAAB CPT: 83516 x2 Performing Lab: ARUP Reported: MPO PR3	ANCA PANEL (VASCULITIS) W/ RFLX TITER EAP: LAB6431 SQ Code: ANCRFA CPT: 83516 x 2 Performing Lab: ARUP - 3003746 Reported: MPO PR3 Reflex Anti-Neutrophil Cyto Ab, IgG EAP: LAB458 SQ Code: ANCIGG CPT: 86255 Performing Lab: ARUP - 3003747 Reported: ANCA Pattern/ANCA Titer
	Vasculitis Panel (New) EAP: LAB6033 SQ Code: ANCAPA CPT: 85245 Performing Lab: ARUP - 3003745 Reported: ANCA Pattern/ANCA Titer MPO PR3
	MPO/PR-3 (ANCA) Antibodies (Still available independently) EAP: LAB3503 SQ Code: ANCAAB CPT: 83516 x2 Performing Lab: ARUP Reported: MPO PR3

If you have any questions, please call the UnityPoint Health - Meriter Laboratories Client Services Department at 608-417-6529 or 1-800-236-0465.